



## Incorrect Tire Size MAY LEAD TO DAMAGED FUEL PUMP HARNESS

**TECH LINK** 2023

**2023 ENGINE OIL CAPACITIES (IMPERIAL FLUIDS) - U.S. and Canada only**

MODEL	ENGINE	IMP.	IMP. - LITERS	IMP. - CONSUMPTION	REMARKS - VISCOSITY	SEE FUEL PUMP REPLACEMENT
Blazer	3.6L I6	4.5	5.3	0.5	SAE 5W-30	PT0108
	2.8L I4	3.5	4.2	0.4	SAE 5W-30	PT0108
Camaro	2.0L I4	3.5	4.2	0.4	SAE 5W-30	PT0108
	2.0L I4	3.5	4.2	0.4	SAE 5W-30	PT0108
Corvette	3.6L I6	4.5	5.3	0.5	SAE 5W-30	PT0108
	3.6L I6	4.5	5.3	0.5	SAE 5W-30	PT0108
Equinox	3.6L I6	4.5	5.3	0.5	SAE 5W-30	PT0108
	3.6L I6	4.5	5.3	0.5	SAE 5W-30	PT0108
Malibu	3.6L I6	4.5	5.3	0.5	SAE 5W-30	PT0108
	3.6L I6	4.5	5.3	0.5	SAE 5W-30	PT0108
Traverse	3.6L I6	4.5	5.3	0.5	SAE 5W-30	PT0108
	3.6L I6	4.5	5.3	0.5	SAE 5W-30	PT0108

**New 2023 Engine Oil  
Capacities Chart Now  
Available**

see page 3



**Fluid Leak at the Rear  
of the Transmission**

see page 4

*Incorrect Tire Size May Lead to  
Damaged Fuel Pump Harness . . . . . 2*

*Body Control Module  
Malfunction DTC . . . . . 5*

*Brake Pedal Play May  
Affect Cruise Control  
Operation . . . . . 6*

*Radiator Air Baffle  
Squeak Sound . . . . . 7*

*DTCs Set After Wheel Speed  
Sensor Replacement . . . . . 7*

# Incorrect Tire Size

## May Lead to Damaged Fuel Pump Harness

An extended engine crank or reduced engine power condition may be the result of incorrect tires mounted on some 2016-2023 Camaro SS, Camaro SS 1LE (RPO A1Y); 2017-2023 Camaro ZL1; and 2018-2023 Camaro ZL1 1LE (RPO A1Z) models.



Camaro ZL1

If these conditions are present, inspect the left-rear wheelhouse liner for a rub-through condition caused by the installation of larger, incorrect tires. These conditions may be difficult to diagnose, so it's important to check the tires installed on the vehicle. Some customers may have installed larger, aftermarket tires.



Inspect the left-rear wheelhouse liner.

The oversized tires may damage the body-to-fuel pump harness and the chassis module-to-fuel pump connector X350. In addition, the damaged harness may cause an intermittent short during heavy acceleration and the F35RA fuse may be blown in the rear fuse block.

If the concern is caused by a rub-through condition and the vehicle is not equipped with the original equipment (OE) tires, advise the customer of the importance to use the same tire size and manufacturer with which the vehicle was originally equipped. Damage caused by incorrect, oversized tires is not covered by the New Vehicle Limited Warranty.



Damaged body-to-fuel pump harness




**TIP:** When checking the tires, always check the tire manufacturer too. The same tire size, but from a different manufacturer, could result in a difference of up to 10 mm in actual tire size.

If the engine performance concerns are caused by a rub-through condition at the left-rear wheelhouse liner, yet the vehicle is equipped with the OE tires, repair the harness and submit a field product report. Be sure to include photos and tire information in the report.

For additional information, including OE tire information for Camaro SS and ZL1 models, refer to Bulletin #20-NA-104.

► Thanks to Kurtis Hoezee


# New 2023 Engine Oil Capacities Chart Now Available

<div>   <div>2023</div> </div>						
2023 ENGINE OIL CAPACITIES (WITH FILTER) – U.S. and Canada only						
<div>  </div>						
MODEL	ENGINE	RPO	SPEC - LITERS	SPEC - QUARTS	GRADE/ VISCOSITY	OIL FILTER - ACDELCO PN
Blazer	2.0L L4	LSY	5.0	5.3	dexos1 0W-20	PF66
	3.6L V6	LGX	5.7	6.0	dexos1 5W-30	UPF63R
Camaro	2.0L L4	LTG	4.7	5.0	dexos1 5W-30	PF64
		LTG with Y4Q (oil cooler)	5.2	5.5	dexos1 5W-30	PF64
	3.6L V6	LGX	5.7	6.0	dexos1 5W-30	UPF63R
	6.2L V8	LT1, LT4	9.5	10.0	dexosR 0W-40	PF64
Colorado	2.7L L4	L2R, L3B	5.2	5.5	dexos1 5W-30	PF66
Corvette	6.2L V8	LT2	7.1	7.5	dexosR 0W-40	PF64
	5.5L V8	LT6	7.6	8.0	dexosR 5W-50	PF2269G
Equinox	1.5L L4 FWD	LSD	4.0	4.2	dexos1 0W-20	PF64
	1.5L L4 AWD	LSD	5.0	5.3	dexos1 0W-20	PF64
Express	4.3L V6	LV1	5.7	6.0	dexos1 5W-30	PF63
	6.6L V8	L8T	7.6	8.0	dexos1 5W-30	PF63
Low Cab Forward	5.2L L4 Diesel	4HK1	11.0	11.6	CK-4 10W-40	98298404 (GM PN)

The new TechLink 2023MY Engine Oil Capacities chart is now available under the Reference Charts menu. The chart includes engine, RPO, specifications (liters and quarts), oil viscosity and engine oil filter specs for 2023 Chevrolet, Buick, GMC and Cadillac models.

For additional information on the appropriate engine oil and oil filter for a particular engine application, refer to the appropriate Service Information. Under the Maintenance Items link at the top of the Service Category Type page, the Approximate Fluid Capacities, Fluid and Lubricant Recommendations, and Maintenance Replacement Parts sections provide fluid and filter specifications. There also is a link for the Oil Life System Resetting procedure.

The Maintenance Items link also provides quick access to a variety of other maintenance information.


**Service Information**

2023 Buick Encore - AWD / Buick Service Manual N America 13082933 | Maintenance Items

Maintenance Procedure	Link
Approximate Fluid Capacities	<a href="#">Approximate Fluid Capacities</a>
Fluid and Lubricant Recommendations	<a href="#">Fluid and Lubricant Recommendations</a>
Maintenance Replacement Parts	<a href="#">Maintenance Replacement Parts</a>
Oil Air Filter Life System Resetting	<a href="#">Oil Air Filter Life System Resetting</a>
Oil Life System Resetting	<a href="#">Oil Life System Resetting</a>
Tire Rotation	<a href="#">Tire Rotation</a>
Tire Pressure Indicator Sensor Learn	<a href="#">Tire Pressure Indicator Sensor Learn</a>
Passenger Compartment Air Filter Replacement	<a href="#">Passenger Compartment Air Filter Replacement</a>
Brake Pad Inspection	<a href="#">Brake Pad Inspection</a>
Cooling System Draining and Filling	<a href="#">Cooling System Draining and Filling</a>
Hydraulic Brake System Bleeding	<a href="#">Hydraulic Brake System Bleeding</a>
Air Cleaner Element Replacement - 3.6L (LPT)	<a href="#">Air Cleaner Element Replacement</a>
Spark Plug Replacement - 3.6L (LPT)	<a href="#">Spark Plug Replacement</a>

Maintenance items link in Service Information.

More information also can be found in the Owner's Manual, available from the Vehicle Publication page in Service Information.

► Thanks to Tracy Flood and John Kopeck



# Fluid Leak at the Rear of the Transmission

A transmission fluid leak may be seen on some 2022 Silverado, Tahoe, Suburban, Sierra, Yukon and Escalade models equipped with the 10L80 10-speed automatic transmission (RPO MHS, MHT, MQB, MQC). One or more of the rear case plugs on the transmission may be leaking.

Inspect the rear of the transmission for evidence of transmission fluid at the case plugs. To help confirm the leak source is the case plug, use a light looking from the right side of the transmission between the transmission crossmember and the transmission case.




Rear case plugs on the transmission (4WD shown)

If one or both case plugs are found to be leaking, remove the transmission crossmember support and mount to gain access to the plugs (4WD shown). Only replace a plug if it is leaking. Refer to the appropriate Service Information for the complete service procedure.



Rear case plugs

Remove and discard a leaking plug and then clean the threaded hole of any residual oil with a clean, lint-free shop towel.



Remove and discard a leaking plug.

**TIP:** Not all of the residual oil will be removed in the cleaning process. Do not use brake clean-type solvents to clean the threaded plug hole.

Before installing a new plug, apply a small bead of ACDelco thread sealant. Install the new plug and torque to 11 lb.-ft. Clean around the plug.



Apply ACDelco thread sealant to new plug.

CONTINUED ON PAGE 5

# Body Control Module Malfunction DTC

Some 2020-2023 CT4, CT5, Corvette; 2021-2023 Envision, Escalade, Tahoe, Suburban, Yukon; and 2022 Silverado 1500 and Sierra 1500 models may have DTC P0606 (Control Module Processor Performance) set in the Body Control Module (BCM) along with an illuminated Check Engine MIL. There also may be performance concerns with the HVAC and lighting systems as well as several Driver Information Center messages displayed.


These conditions may be due to the BCM software or an incorrect BCM Program Flow Monitoring Status parameter. DTC P0606 will set if there is an internal malfunction or system programming malfunction in the BCM.

To review the parameters using GDS2, select the following path: Module Diagnostics > Body Control Module > Identification Information > Internal Control Module Performance Data. If the Program Flow Monitoring Status parameter is “active” and all other parameters are “inactive,” update the BCM with the latest calibration using SPS.

After programming the BCM, or if the BCM was up to date, review the Program Flow Monitoring Status parameter again.

**Program Flow Monitoring Status after BCM programming:**

- If the Program Flow Monitoring Status parameter is still listed as “active” and all other parameters are listed as “inactive,” clear all codes. No other repairs are necessary. DTC P0606



Parameter Name	Value	Unit	Control Module
Random Access Memory Test Status	Passed		Body Control Module
Read Only Memory Test Status	Passed		Body Control Module
Configuration Register Fault Status	Inactive		Body Control Module
Program Flow Monitoring Status	Inactive		Body Control Module
Stack Fault Status	Inactive		Body Control Module
Lock Step Fault Status	Inactive		Body Control Module
Algorithm Fault Status	Inactive		Body Control Module

Check the Program Flow Monitoring Status parameter using GDS2.

may remain in the BCM. Do not replace the BCM. Additional information from GM Engineering will be released when available.

- If the Program Flow Monitoring Status parameter and all other parameters are listed as “inactive,” clear any codes. Repairs are complete.
- If the Program Flow Monitoring Status reads “active” or “inactive” while any other parameters read “active,” follow the diagnostic procedures for DTC P0606 in the appropriate Service Information.

Refer to #PIT5946 for additional information.

► Thanks to Paul Radzwilowicz

FLUID LEAK, CONT.



Clean the area around the new plug and check the transmission fluid level.

Complete repairs by reinstalling the transmission crossmember and then checking the transmission fluid level. Add transmission fluid ULV if needed following the procedure in Service Information. For additional information and part numbers, refer to #PIP5872.

► Thanks to Tom Ellison and Mark Gordon

# Brake Pedal Play May Affect Cruise Control Operation


Excessive brake pedal free play may cause the cruise control to not set or resume after braking on some 2022 Encore GX and Trailblazer models. It may be necessary to pull up on the brake pedal to engage cruise control. These conditions may be intermittent and cruise control operation may return to normal after the vehicle is turned off and restarted.

If the brake pedal moves rearward during acceleration, it may cause an inaccurate Learned Release Position in the Engine Control Module (ECM) and the ECM Brake Pedal Position Sensor will show a value of 6% pedal travel or greater. As a result, the parameter for Cruise Control Inhibit Reason will show Brake Pedal Applied, causing cruise control to be disabled.




The brake pedal may move rearward during acceleration.

To verify the brake pedal concern, monitor the Brake Pedal Position Sensor (BPPS) Learned Released Position and the Brake Pedal Position Sensor parameters in GDS 2 during a test drive



Vehicle Speed Sensor (yellow line), Brake Pedal Position Sensor (red line), BPPS Learned Released Position (green line) and Brake Pedal Position Sensor (blue line)

with cruise control engaged. The data, found under ECM > Data Display > Automatic Transmission, shows the ECM is constantly learning. During acceleration, if there is movement in the brake pedal, the ECM will relearn the new, incorrect values that indicate the brake pedal is applied.



Brake and accelerator pedal assembly

While performing a test drive, accelerate several times from 0-50 MPH. In the GDS 2 data, while the vehicle is accelerating (yellow line), the Brake Pedal Position Sensor (red line) will drop to a lower value than the normal release position, which causes a corresponding drop in the BPPS Learned Released Position (green line) value. The ECM will show some percentage of travel greater than zero when traveling at a steady speed with the pedal released (blue line). Under these circumstances, the parameter for Cruise Control Inhibit Reason will show Brake Pedal Applied.

If these conditions are found, the brake and accelerator pedal assembly should be replaced.

For more details, including additional information about the GDS 2 parameters, a video of the brake pedal movement and related part numbers, refer to Bulletin #22-NA-097.


► Thanks to Frank Jakubiec




# Radiator Air Baffle Squeak Sound

A squeak sound may be heard coming from the front of the vehicle on some 2019-2023 Camaro models equipped with the 2.0L I4 turbo engine (RPO LTG) or the 3.6L V6 engine (RPO LGX). The sound emanates from the passenger's side of the vehicle while driving over bumps. It also may be more noticeable once the engine has reached normal operating temperature.

The squeak sound on these engines may be caused by the radiator air baffle on the right side of the vehicle contacting the core support.



Radiator air side baffle



The radiator air baffle may be contacting the core support in two areas.

If this sound is heard, verify that the radiator air baffle is rubbing on the core support. There are two common areas where contact may occur. If there is contact, material should be trimmed from the air baffle in order to create more clearance between the baffle and the core support.

CONTINUED ON PAGE 8


## DTCs Set After Wheel Speed Sensor Replacement

The right and left front wheel speed sensors on 2019-2023 Silverado and Sierra trucks look very similar. When replacing a front wheel speed sensor, be sure to verify the correct wheel speed sensor part number before installation.

Incorrectly installed sensors will not properly sense the magnetic encoder ring located on the wheel bearing assemblies. As a result, a right front wheel speed sensor cannot be installed on the left side of the vehicle, or vice versa.

An incorrect wheel speed sensor may result in a number of DTCs setting, including wheel speed sensor correlation DTCs C0505, C050B, C0511, C0517 and wheel speed sensor circuit DTCs C0501, C0502, C0503, C0504, C0507, C0508, C0509, C050D, C050E, C050F, C0510, C0513, C0514, C0515, C0516 and/or C050A.

Installation of the wrong sensor also may lead to the unnecessary replacement of several other parts, such as the brake system control module, wheel bearings, other wheel speed sensors, pigtail connectors, etc.



Front wheel speed sensor (#3) shown on the left side of the vehicle.

CONTINUED ON PAGE 8


## RADIATOR AIR BAFFLE, CONT.

After removing the right-side radiator air side baffle, measure inboard and mark the horizontal and vertical edges as noted in Bulletin #22-NA-178.

Once measurements have been made, cut along the marked lines to modify the shape of the air baffle. Reinstall the radiator air side baffle and make sure there is proper clearance between the air baffle and the radiator core support.

Refer to Bulletin #22-NA-178 for additional information.

► Thanks to Kurtis Hoezee



Modify the air baffle to eliminate contact with the core support.


## DTCS SET, CONT.

If a front wheel speed sensor is replaced and a wheel speed sensor DTC sets for the same side, check that the correct part number for the front wheel speed sensor has been installed. With the correct wheel speed sensor installed, the flat side


of the sensor tip will be orientated towards the wheel bearing magnetic encoder ring.

Refer to #PIT5950 for additional information.

► Thanks to Jim Will



Right front wheel speed sensor (#1)



Left front wheel speed sensor (#2)

## TECH LINK

GM TechLink is published for all GM retail technicians and service consultants to provide timely information to help increase knowledge about GM products and improve the performance of the service department.

**Publisher:**  
Ravishankar Bommanahally  
GM Customer Care and Aftersales

**Editor:**  
Lisa G. Scott  
GM Customer Care and Aftersales

**Technical Editor:**  
Mark Spencer  
mspencer@gpstrategies.com

**Production Manager:**  
Marie Meredith

**Creative Design:**  
5by5 Design LLC  
dkelly@5by5dzn.com

**Write to:**  
TechLink  
PO Box 500, Troy, MI 48007-0500

**GM TechLink on the Web:**  
GM GlobalConnect

General Motors service tips are intended for use by professional technicians, not a "do-it-yourselfer." They are written to inform those technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the information applies to your vehicle or that your vehicle will have that condition. See a General Motors dealer servicing your brand of General Motors vehicle for information on whether your vehicle may benefit from the information. Inclusion in this publication is not necessarily an endorsement of the individual or the company. All information contained herein is based on the latest information available at the time of publication and is subject to change without notice.

Copyright © 2022 General Motors. All rights reserved.